


STATE OF UTAH
DEPARTMENT OF NATURAL RESOURCES
DIVISION OF OIL, GAS AND MINING
355 West North Temple
3 Triad Center, Suite 350
Salt Lake City, Utah 84180-1203
Telephone: (801) 538-5340
Fax: (801) 359-3940



ANNUAL REPORT OF MINING OPERATIONS

The informational requirements of this form are based on provisions of the Mined Land Reclamation Act, Title 40-8, Utah Code Annotated 1953, as amended, and the General Rules as promulgated under the Utah Minerals Regulatory Program. An operator conducting mining operations under a Notice of Intention must file an annual operations and progress report (FORM MR-AR) with the Division.

I. General Information

1. Report Time Period: From (mo./yr.) Jan. 1994 To (mo./yr.) Jan. 1995
2. DOGM File Number (Mine No): M/015/050
3. Mine Name: Georgia Pacific - San Rafael / Eagle Canyon Quarry
4. Mineral(s) Mined (or permitted to mine): Gypsum
5. Type of mine ☒ Surface Mine or ☐ Underground Mine
6. Legal Description (Location of Lands Affected):
SW 1/4, SW 1/4, Section 19, Township 22-S, Range 9-E
SW 1/4, SE 1/4, Section 24, Township 22-S, Range 8-E
1/4, 1/4, Section , Township , Range
7. Name of Operator or Company: Georgia Pacific Corp
8. Permanent Street Address : P.O. Box 570080
City, State, Zip: Sigurd, Utah 84657-0080
Phone: 801-896-5406
9. Company Representative (or designated operator):
Name: F. Lamar Christensen
Title: Plant Manager
Business Address: P.O. Box 570080
City, State, Zip: Sigurd, Utah 84657-0080
Phone: 801-896-5406

☒ Please check if any of the above information has changed since previous year.

II. Mining and Reclamation

1. Was the mine active during the past year? Yes ☒ No ☐
2. If active, how much ore or mineral was mined? 43,221 Ton

3. How much additional acreage was disturbed during the past year? 14.26
4. Briefly describe any new or additional surface disturbances that occurred during the past year. This description should include the type of work performed, and volume of material moved.

We removed 7506 cu. yds. of overburden from our mined area and uncovered 43,221 Tons of rock.

5. How much acreage was reclaimed during the past year? None

6. Briefly describe the reclamation work performed during the past year. This description should include methods employed, and an evaluation of the results.

We have started reclamation on approx. 3 acres. Presently about 35% complete. This is being accomplished using a loader and Dozer To backfill the mined area.

7. What is the total disturbed acreage at years end? 23.26

8. Briefly summarize any mining and/or reclamation plans for the upcoming year.

Our plan is to continue mining and reclaiming during 1995.

NOTE: Section III., "Additional Information" applies only to large mining operations.

III. Additional Information

1. An updated surface facilities map should be attached if there have been significant changes since the previous map was submitted.
2. Any monitoring results or other reports that are required under the terms of the approved notice of intention should also be attached.

IV. Signature Requirement

I hereby certify that the foregoing is true and correct.

Name (Typed or Print): F. Lamar Christensen

Title of Operator: Plant Manager

Signature of Operator: F. L. Christensen

Date: Jan. 31, 1995